

Address	Noted Issues 5- 2017
6001 Mia	Cracking along N side of entry way, weather strip N side of garage broken
6002 Mia	Crack at joint w/ patio cover, chip in corner of patio, crack W side of patio cover, crack on archway
6003 Mia	Crack base of N PW, separation a N PW, swelling and cracking at joint of S PW
6004 Mia	Cracks on N PW (both sides), cracks on S entry wall, cracks in entry way
6005 Mia	Cracking base of S PW, horizontal crack S side garage door
6006 Mia	Slight cracking around FP vent and spigot, cracks around window, cracks on N PW (both sides) cracks on garage wall, fine cracks on entry wall
6007 Mia	Back window, N bottom corner has cracking
6008 Maj	Separation N PW, crack UR Bedroom slider, dings S side Bedroom slider, separation at stucco roofline, light separation at masonry below electric meter
6008 Mia	Cracks around window, slider, N PW (both sides), entry divider and entry wall
6010 Maj	Crack at S PW joint, cracks w/ separation at base of S PW (both sides), slight separation of masonry S Side, crack UR garage roofline, UL entry door, center over garage door
6010 Mia	Cracks around patch, N PW (both sides) and on entry walls
6011 Mia	Rust showing, start of separation N PW, small crack center of S wall
6012 Maj	Downspout loose screw not holding in place, N wall (base) nasty swelling w/ cracks, slight crack along joint S PW
6012 Mia	Cracks on entry wall
6013 Mia	Damage to S side of garage opening, pitting adj. to gas meter
6013 Vin	Fine crack at base of Bay Window, base of slider (LR)
6014 Maj	Cracks on wall beneath window, ding to support S side entry
6015 Mia	Cracks on PW, both sides, Cracking top of S of garage door, crack adj to electric meter, separation t top of bay window
6015 Vin	No problems
6016 Maj	Damage to slider trim
6016 Mia	Cracks on joint w/ patio cover, on PW (both sides)
6017 Vin	No problems
6018 Maj	Crack flowing from base beneath elect outlet, base of N PW
6018 Mia	Cracks on 2nd level above slider, on PW (both sides)
6019 Mia	Rot on fascia, south side
6019 Vin	Crack above S Bay Window
6020 Maj	No problems
6020 Mia	Cracks on 2nd level above slider, by window, on N PW (both sides)some separation of PW from wall, N corner of garage
6021 Mia	
6021 Vin	Crack at base of N entry wall, settling of entry concrete , under rear window, LR bathroom window, at base of center Bay Window
6021/6023 Mia	Separation of PW plus cracks on North PW
6022 Maj	Crack by pad and spigot N side
6022 Mia	Cracks at corner of slider, PW both sides both lower corners of window
6023 Mia	Trim at base of slider, crack in corner of slider, Swelling of wood on S side of garage, crack front corner of facia
6023 Vin	Crack between facia and stucco N entry wall by garage, missing stucco at base of N PW
6024 Mia	Small crack on garage wall
9201 Vin	No problems

9203 Vin	Fine cracks both sides of E Bay Window, on W side PW at joint w/ house
9205 Vin	Fine cracks at base of center Bay Window, base of E wall near bathroom window
9206 Vin	Cracks at base of S PW, inside of PW, joint btwn PW and E wall, E wall, joint of E Bay Window
9207 Maj	Lawn mower dents on PW (both sides)
9207 Vin	Crack at electric outlet (rear), upper corner of PW (both sides), ding in corner of PW, corners of bathroom window, numerous base of W wall, center Bay Window
9209 Maj	Crack LL corner of window, numerous fine on W wall, all windows have cracks at corners under Bay Window (W side), windows of NW patio
9209 Vin	Crack on W PW
9210 Vin	Cracks on W wall, by windows W wall, S wall, PW
9303 Vin	Small crack at joint of original wall and patio cover (E side), top of patio wall, base of sliders (both sides), W wall numerous--some large
9305 Maj	Cracks around sealed window W side, on W wall, both sides of entry arch, E wall by bathroom window plus other small, Patio enclosure (both sides), LL slider trim
9305 Vin	Cracks on all walls, cracks at masonry joint near electric meter, fine cracks at base of E wall, needs to trim evergreen on E side , separation of E PW (both sides), Cracks on both sides of slider, ding a L corner of W PW
9306 Maj	Cracks around electric meter, hole on W wall of patio inset
9306 Vin	Flaking paint on garage man entry
9307 Maj	No problems
9307 Vin	Cracks on all walls
9308 Maj	Cracks under S window, cracks along E side wall
9308 Vin	Cracks on E wall (extensive fine)
9309 Maj	No problems
9309 Vin	Crack at joint between entry and garage wall, fine alone base of E Wall
9310 Maj	Cracks on W wall around AC and Gas (numerous, fine under S side window
9310 Vin	Cracks (fine) on PW, W wall, E entry wall
9311 Maj	Crack in front Masonry
9311 Vin	Separation of W PW (both sides), dine crack at base of E wall, E corner of entry all, base of electric meter, E PW
9312 Maj	Crack at base of slider, ding at base of rear window, ding near corner of S wall, separation between entry and E wall, crack at UE garage roofline
9312 Vin	Major crack in Masonry E wall entry, crack on E side under bathroom window
9313 Maj	Damage at corner of Tr window (W side) crack at LL/LR slider trim
9313 Vin	Fine crack at electric meter, ding on E side entry corners, damage to PW (both sides), separation at joint of PW and wall
9314 Maj	Crack along base of E entry, above entry
9314 Vin	Crack under bathroom window (W side), settling of entry concrete, cracks on entryway, separation at abase of entry way arch
9315 Maj	Crack at LR slider
9315 Vin	No problems
9316 Maj	Crack at W PW base joint
9316 Vin	Separation at base of rock (E entry), needs screens reset on S side
9317 Maj	Fine cracks at LL slider
9318 Maj	Crack above electric meter, L Bathroom window
9318 Vin	Crack at base of W wall, base of window LR, at roofline E side, AC may be leaking (oil on wall) AC electric box loose
9320 Maj	Patched crack on W PW base, ding on S wall cracks by window S side, along base of E wall
9401 Maj	No problems
9401 Vin	Gaps around AC entry
9402 Maj	Dings on entry wall, crack next to drain spout , corners of windows W side, Bedroom windows, transom windows, din to slider trim
9402 Vin	Cracks on E side base of wall, a LR slider

9403 Maj	No problems
9403 Vin	Fine crack a NW corner base, damage at AC entry, damage on N wall E of Slider
9404 Maj	Fine crack UL slider, stucco separating from front pad
9404 Vin	Cracks a LL of slider, base of S wall, W wall (numerous), crack in masonry at entry wall, gap between facia and stucco over garage
9405 Maj	No problems
9405 Vin	Fine cracks at base of E wall
9406 Maj	Crack above Eave on E side patio
9406 Vin	Chip on corner of garage and entry, fine cracks on E wall
9407 Maj	Fine crack PW W side, LL/LR Window W side
9407 Vin	Fine cracks at base of W wall, shrinkage UL garage facia
9408 Maj	Ding at garbage pad, cracks along W wall base (fine)
9408 Vin	Dings in S wall (W of slider), crack in corner W PW, fine cracks at base of W wall, LL/UL window on W wall, E entry wall nr masonry
9409 Vin	Crack UL archway, UL entry wall by door, hairline W side patio joint, mower damage to W PW
9411 Vin	Crack UL above entry door at corner of walls
9413 Vin	Cracks both sides of entry arch
9415 Vin	Cracks in trim of Bay windows, E wall under large window, base of E wall, base of N wall by bedroom window, near top of PW, ding base of E Wall (NE)
9417 Vin	Separation of W PW, cracks at base of N window, ugly patch on E PW, crack on E PW, center of upper garage trim
9419 Vin	Fine cracks UL of electric meter, along base of E Bay Window, LL o W Bay Window, numerous along base of E Wall , E PW has separation
9501 Vin	Swelling at base of W PW
9503 Vin	cracks at base of slider trim
9505 Vin	Cracks on E PW (both sides), cracks adj to electric meter
9507 Vin	Cracks on E PW (both sides)
9511 Vin	Cracks at joint W PW, cracks on E wall (fine), cracks on E garage wall
9512 Mia	Crack W PW and along top of PW
9513 Vin	Cracks by electric meter and wall to entry, numerous small cracks on W wall
9514 Mia	Cracks on PWs, cracks around electric meter
9516 Mia	Crack on E PW, cracks on E side of garage door
9601 Mia	Cracks E side garage, cracks W side garage with separation next to 9603
9602 Vin	Cracks on W PW, serious flaking on window trim , leaking yard hydrant
9603 Mia	Cracks on W PW (both sides), garage separation near base
9604 Mia	Cracking o n garage wall, horizontal cracks on W wall
9604 Vin	No problems
9605 Mia	Cracks on W PW (both sides), cracks next to front entry
9605 Vin	
9606 Mia	No access to patio area, cracks on walls W of garage door, crack, vertical from water spigot, damage to base of W entry wall
9606 Vin	Cracks on Bay Window, crack at E PW joint(outer) chips and holes in entry way (garage side)
9607 Mia	Cracks on garage wall, east side
9607 Vin	Dings on W garage corner
9608 Mia	Cracks on E PW, Crack frond of doorway, cracks on E entry
9609 Vin	Crack on center Bay Window trim
9611 Mia	Crack on E side of entry and on E wall, garage trim broken
9612 Mia	Back, cracks at corner of window, and on slider door, separation on W PW plus cracks

9612 Vin	No problems
9613 Mia	Rust on E side PW and cracks, cracks on W PW (both sides), numerous cracks next to AC
9613 Vin	
9614 Mia	Crack at base of W PW, separation of W PW, crack at base of slider
9614 Vin	Major crack at joint on E PW, Cracks on E PW
9615 Mia	Cracks on W PW (serious) (both sides), cracks on both sides of entry way
9615 Vin	Separation of W PW (both sides), separation of E PW (both sides), cracks on E PW (both sides), cracks on E entry wall
9616 Vin	No problems
9617 Mia	Cracks on W Bay Window, cracks on E side of entry way, broken trim E side of garage
9618 Mia	
9619 Vin	No noted problems
9620 Mia	
9621 Mia	Rust on Bay Window/garage at entry, broken dryer vent, handle missing from slider, cracks/separation on E PW, crack W side garage
9621 Vin	Major cracks a E side juncture, dent on W side of entry door
9622 Mia	No noted problems
9622 Vin	Rust spots east of slider
9623 Mia	Major crack and separation E PW , minor cracks on W PW (both sides), broken trim on garage, crack near entry on garage wall
9623 Vin	No noted problems
9624 Vin	Major crack at joint on E PW , cracks at S end PW (both sides)
9625 Mia	Crack next to Electric meter, cracks next to entry on garage wall
9626 Mia	Crack on E roof line, cracks on W PW, Cracks on W side of entry
9626 Vin	
9627 Mia	Crack on E PW and separation, cracks around slider, clogged dryer vent, separation btwn, garage and entry, cracks in garage wall, cracks and rust on support pillar
9627 Vin	
9628 Mia	Cracks of E PW, Cracks on W PW, Cracks on W side of garage, Cracks of entry way (both sides)
9628 Vin	Damage to entry concrete
9629 Vin	
9630 Mia	Cracks on E PW
9631 Vin	Damage to trim and vertical crack from N side of trim
9702 Mia	Cracks on E side garage to entry, separation of E PW, cracks on W PW, crack near electric meter
9703 Vin	Cracks at base of slider trim, damage to E wall (previous owner caused)
9704 Mia	Cracks on E PW, separation of E PW, cracks on W PW
9705 Vin	Cracks W PW, cracks on slider trim, cracks on N entry wall and garage wall
9706 Mia	Cracks on W PW, crack nest to Fire place exhaust, separation of W PW, cracks on W PW, crack at electric meter
9707 Mia	Crack on garage walls both S and W, fine cracks N PW (both sides)
9707 Vin	Serious cracks W PW, serious cracks E PW (also rust) , cracks by AC entry and phone entry
9708 Mia	Cracks on E PW, cracks on W PW (both sides), crack by small window W side, cracks a Electric service entry, cracks east garage wall
9709 Mia	Crack on N PW (both sides), cracks on N entry wall and garage wall
9709 Vin	Crack below center bay window, swelling of W side of slider, serious cracking of E PW
9711 Mia	Crack next to AC entry, cracks on entry pillar, cracks by phone entry
9715 Vin	Cracks by electric meter, separation base of Bay Window, AC penetration, base of window corners, base of E wall, UL corner slider, PW (both sides), separation at roof NE corner

9716 Vin	Crack on W side of entry, cracks and separation W PW (both sides)
9717 Mia	Cracks W side of entry, at gas line penetration, at patio cover and W PW
9717 Vin	Cracks around FP vent, around slider, PW, W & E entry walls, E side garage
9718 Vin	Cracks on W PW (both sides), cracks by front of garage door cracks on both sides of entry
9719 Mia	Cracks E PW, W PW (both sides), upper L garage door, both sides entry way, separation on E entry wall
9719 Vin	Cracks around small window
9720 Vin	Cracks on W PW (both sides), crack under Bathroom window, cracks front garage wall
9721 Mia	Crack on entry (garage side)
9722 Vin	Crack on garage wall
9723 Mia	
9801 Mia	Fine Crack W entry wall, W Bay Window UR, center Bay Window W side, AC penetration, Lint at Dryer Vent (needs replaced), W PW (both sides)
9802 Vin	Dent center Bay Window, cracks in PW (both sides) but worse on W side
9803 Mia	Cracks on entry wall (both sides), entry arch
9804 Vin	Cracks on wall and window frame, cracks on W PW (both sides), cracks on garage wall E side of entry
9805 Mia	Cracks W PW, damage to back window trim LL, E PW (both sides), garage wall, E entry side, damage to arbor trim
9806 Vin	Dent in wall E of slider, cracks on W PW (both sides) small crack at garage joint, numerous cracks on garage wall E side of entry
9807 Mia	Cracks entry wall (garage side)
9808 Vin	Fine crack on W Bay Window, fine cracks on garage wall (entry), fine cracks E side of garage door
9810 Mia	Cracks at AC entry, W entry wall
9811 Mia	Cracks W entry wall (fine), W PW (both sides), flaking trim W side slider
9811 Vin	Cracks W entry wall, windows E side
9812 Mia	Cracks on PW, 2nd level windows, E side garage wall, on wall inside entry
9812 Vin	Fine cracks PW both sides
9813 Mia	Cracks over slider, W PW (both sides), entry way (both sides)
9813 Vin	Cracks on PW, 2nd level trim
9814 Mia	Cracks on PW, SE corner window LL, cracks on W entry wall
9814 Vin	Fine cracks PW both sides, fine crack down from W corner of window, cracks going up frame center of garage, cracks both sides of entry
9815 Mia	Cracks on W garage wall, needs trim bush on E side to see house number, cracks E side entry
9815 Vin	Cracks on E PW, W PW (both sides), entry walls (both sides)
9816 Mia	Cracks on E entry wall, broken dryer vent, small cracks around slider, cracks on PW (both sides)
9816 Vin	Fine cracks on PW (both sides), cracks on walls both sides of entry, cracks on front of garage (both sides)
9817 Mia	Cracks in W PW, needs Dryer Vent replaced, cracks around gig Window (W side), E side entry wall
9817 Vin	Cracks between Gas meter and water spigot, E entry wall
9818 Vin	Cracks on W wall by AC, cracks on entry wall (garage side)
9820 Mia	Separation of PW
9821 Mia	Cracks above W Bay Window, damage to corner of Bay Window, cracks at base of E wall, around main window E side, W PW (both sides), W side garage
9821 Vin	Cracks around window trim
9822 Mia	Small separation on E entry wall
9822 Vin	No problems
9823 Mia	Cracks on W PW (both sides), around electric meter
9823 Vin	Crack on E PW, ding to garage trim, dead rose removal, corner shrub trimmed next to house
9824 Mia	Cracks at AC entry, Main window W side, rear window, separation of PW

9824 Vin	No problems
9825 Mia	Cracks on W PW (both sides)
9825 Vin	Cracks around windows W side
9826 Vin	No problems
9827 Mia	Cracks on E entry at electric meter, above garage door
9828 Vin	Small crack adj to window on W side LR corner
9901 Vin	Separation around main window E side
9902 Mia	Cracks along joint between house and patio around windows E side
9903 Vin	Crack W side entry arch
9904 Mia	Cracks around rear window
9904 Vin	No problems
9905 Mia	Cracks on W garage wall (numerous), W PW (both sides)
9905 Vin	No problems
9906 Mia	Cracks around slider, separation of PW (both sides), damage above garage door, damage to trim garage and entry
9906 Vin	Crack on wall adj to E PW
9907 Mia	Cracks on W PW (both sides), on window trim, by telephone and electric meter
9907 Vin	Cracks around windows W side, around AC entry, trim of Bay Window
9908 Mia	Cracks by windows W side, separation at patio cover, crack by S window LL
9908 Vin	Needs caulking around slider
9909 Mia	Cracks on W PW (both sides), W garage wall near entry
9910 Vin	No problems
9911 Mia	Cracks on wall and around windows, by telephone and electric entry, on garage wall
9914 Vin	No problems
9916 Vin	No problems
9918 Vin	Small crack on E PW
9920 Vin	No problems
Palazzo	Chip in trim at SW corner